



Av. Europa, nº 12
17800 OLOT
(Girona) SPAIN

Tel. (+ 34) 972 265 100
Fax (+ 34) 972 266 366

xucla@xucla.es
www.xucla.es

ISO 9001

BUREAU VERITAS
Certification



Code	Description
031043	COMPL.COIL CV1000

Tecnic description

Stainless steel construction AISI 316
Heat exchanger by means of a tubular coil situated into the tank and under it.
Steam feeding formed by a flow valve, colander filter, temperature control by electro valve.
Exit of condensed by purge buoy